SAMPLE REPORT

BMW 3 Series (320d)

2019 · Sedan · Diesel · 140 kW (190 hp)

VIN WBA8E1C5••••23456

Generated on 20 September 2026

Last mileage reading
118,000 km
March 2024

Highest mileage reading
174,200 km
January 2023

Warning signs
2
Details are in the sections

MILEAGE	DAMAGE	THEFT	FINANCE OR LIEN
Discrepancy found	3 found	Not reported	Not reported

USED AS A TAXI	OWNERS	PHOTOS	WARNING SIGNS
Not reported	3	No photos	2 in the summary

The mileage appears lower than in an earlier reading
In March 2024 the car shows 118,000 km, after an earlier reading of 173,000 km. That is 55,000 km lower. It may be a rolled-back odometer or a recording error. Get the difference explained at a garage before you buy.

Vehicle details

The technical details recorded for this VIN.


VIN WBA8E1C5••••23456	Make BMW	Model 3 Series (320d)
Body type Sedan	Fuel Diesel	Power 140 kW (190 hp)
Engine capacity 1995 cm³	Gearbox Automatic, 8-speed	Drive Rear-wheel drive
Manufacture date June 2019	First registration November 2019	Colour Black · Black Sapphire metallic
Emission standard Euro 6d-TEMP	Doors 4	Seats 5

Mileage

The mileage readings found, in date order.

Discrepancy found

Last reading	Highest reading	Readings found	Period
118,000 km	174,200 km	12	2019-2024
March 2024	January 2023	One below the previous highest	Nov 2019 - Mar 2024



DATE	MILEAGE	COUNTRY	EVENT
November 2019	12,000 km	DE Germany	First registration
April 2020	29,500 km	DE Germany	Dealer service
August 2020	41,000 km	DE Germany	Scheduled service
February 2021	58,200 km	DE Germany	Tyre change
March 2021	67,000 km	DE Germany	Damage assessment
June 2021	83,000 km	DE Germany	Roadworthiness test
December 2021	104,500 km	DE Germany	Dealer service
June 2022	138,000 km	DE Germany	Roadworthiness test
September 2022	166,000 km	DE Germany	Damage assessment
October 2022	173,000 km	DE Germany	Reading at a garage
January 2023	174,200 km	DE Germany	Deregistered for export
March 2024	118,000 km below the highest of 174,200 km	RO Romania	Sale listing

Timeline


The events found, in date order.

DATE	EVENT	MILEAGE	COUNTRY
Jun 2019	Manufactured	–	DE Germany
Nov 2019	First registration	12,000 km	DE Germany
Apr 2020	Dealer service	29,500 km	DE Germany
Aug 2020	Scheduled service	41,000 km	DE Germany
Mar 2021	Front left damage, EUR 3,450	67,000 km	DE Germany
Jun 2021	Roadworthiness test, passed	83,000 km	DE Germany
Nov 2021	Recall campaign, engine software	–	DE Germany
Dec 2021	Dealer service	104,500 km	DE Germany
Jun 2022	Roadworthiness test, passed	138,000 km	DE Germany
Sep 2022	Rear damage, EUR 820	166,000 km	DE Germany
Oct 2022	Last reading in Germany	173,000 km	DE Germany
Jan 2023	Deregistered, exported	174,200 km	DE Germany
Feb 2023	Registered in Romania	–	RO Romania
Mar 2024	Sale listing with 118,000 km	118,000 km	RO Romania

Damage

The recorded damage, with the areas affected and the value from the source.

3 damage records



AREAS MARKED ON THE DIAGRAM

#1 Front
#2 Bonnet
#2 Roof and windows
#3 Rear
#1 Front left

The car is seen from above, facing left. The numbers match the damage records below.

Value of all recorded damage: 5,510.00 EUR

1 Collision
March 2021 · DE Germany
3,450.00 EUR damage value

Front left · front bumper · left headlight

Mileage: 67,000 km Severity: moderate

2 Hail
July 2022 · DE Germany
1,240.00 EUR damage value

Bonnet · roof

Mileage: 152,000 km Severity: minor

3 **Collision**
September 2022 · DE Germany

820.00 EUR
damage value

Rear · rear bumper

Mileage: 166,000 km Severity: minor

Values are those in the damage record, in the currency of the country where it was recorded. The areas on the diagram are worked out from the damage description.

Theft and finance

Theft registers, finance and how the car was used.

Theft
Not reported
The VIN does not appear in the theft registers we checked.

Finance or lien
Not reported
No leasing or lien appears in the sources we checked.

Used as a taxi
Not reported
No taxi use appears in the sources we checked.

Total loss
Not reported
In the sources we checked, the car does not appear as recorded as a total loss.

VIN
Valid
The structure of the VIN passed the check.

Owners

The recorded ownership periods, in order.

3 owners



Nov 2019 — report date

1 **Company (fleet)**
Keeper
DE Germany
Nov 2019 - Jan 2023
3 years and 2 months

2 **Private individual**
Keeper
RO Romania
Feb 2023 - Nov 2023
9 months

3 **Private individual**
Keeper
RO Romania
Since December 2023
2 years and 9 months, up to the report date

Service

The recorded service work, in short.

5 entries

DATE	MILEAGE	COUNTRY	WORK
Apr 2020	29,500 km	DE Germany	**Oil and filter change** Engine oil · Oil filter · Cabin (pollen) filter
Aug 2020	41,000 km	DE Germany	**Oil and filter change** Engine oil · Cabin (pollen) filter
Dec 2021	104,500 km	DE Germany	**Front brakes · Brake fluid changed** Front brake pads

May 2022	131,000 km	DE Germany	**Gearbox oil change**
Oct 2022	173,000 km	DE Germany	**Rear brakes** Rear brake discs · Rear brake pads

Each entry is summarised from the source's list of parts and operations. The full list is on the report page.

Recalls

The manufacturer's recall campaigns for the model and year of this car. A dealer for the make can tell you from the VIN whether they were done on this car.

Engine control unit software (emissions) November 2021

Ask a dealer for the make whether the recall work was done on this car.

Sale listings

The listings the car appeared in, with the asking price and the stated mileage.

DATE	STATED MILEAGE	ASKING PRICE
November 2022	173,500 km	27,900.00 EUR
January 2023	174,200 km	25,500.00 EUR
March 2024	118,000 km lower than in an earlier listing	18,900.00 EUR

Equipment

The equipment recorded for this VIN.

16 items

- Navigation Professional
- Heated front seats
- Reversing camera
- Cruise control with speed limiter
- Panoramic roof
- Head-up display
- Keyless start
- Lane keeping assistant
- Adaptive LED headlights
- Front and rear parking sensors
- 3-zone automatic climate control
- Leather sports steering wheel
- 18-inch alloy wheels
- Harman Kardon sound system
- Electrically folding mirrors
- Wireless phone charging

Photos

The photos found for this VIN.

We found no photos for this VIN.
Ask the seller for recent photos and, if you can, see the car in daylight.

Registration

Where and when the car was registered.

Country of registration	Status	First registration
Romania	Registered	November 2019

Registration in Romania	Imported from
February 2023	Germany

Estimated market price

Estimate

A rough value in our estimate, from age, engine, body type and mileage.

Estimated range	In euros, approximately
RON 91,175 - 120,855	€18,345 - €24,317

The report shows damage for this car and the estimate does not account for it: a car with damage usually sells below this value.

A rough estimate worked out from the car's details, not a professional valuation. The real price depends on the actual condition, equipment, service history and demand.

What the car costs to keep

Estimate

Yearly estimate for Romania, from the engine capacity (1,995 cm³), the 2026 Romanian Tax Code and average motor insurance prices.

RCA motor insurance	ITP roadworthiness test	Car tax (1,601 - 2,000 cm³)
RON 950/year	RON 145 every 2 years	RON 216/year

Road vignette (rovinietă)	Servicing and upkeep	Estimated average consumption
RON 139/year	RON 850/year	~6.4 L/100 km

Yearly total (without fuel)
RON 2,228/year

Rough estimates, not quotes: they vary with the local council's rate and the driver's age and no-claims class. Fuel depends on how far you drive and is not in the total.

About this report

The report shows what was recorded in the sources we checked for this VIN. An event that was not reported there does not appear here either. The report does not replace a technical inspection by a mechanic and does not guarantee the condition of the car. Before you buy, take the car to a garage of your choice. Questions: salut@raportauto.ro